



Cleaning	Requirements
Air Scrubbing	Seal the space and provide air-scrubbers in the data hall to ensure that any airborne dust is removed from the air.
Underfloor	Remove dust, particulate and debris from the under floor void. Suggested method to include vacuuming, damp wiping and tacki-wiping as required. Including accessible pipework, containment /cables etc.
Floor Frame	Remove dust, particulate and debris from the floor frame, including the pedestals and stretchers. Suggested method to include vacuuming and damp wiping.
Floor Tile	Remove dust from underside of tile. Suggested method to include vacuuming, damp wiping and tacki-wiping as required.
Floor Tiles Top	Clean floor as required and in accordance with Manufacturers recommendations.
Cable Racks/Trunking	Remove dust from all accessible surfaces. Suggested method to include vacuuming, damp wiping and tacki-wiping as required
Luminaires	Clean all Luminaires. Suggested method dry antistatic dusting.
Air Conditioning Units	All accessible external parts of the CRAC units shall be cleaned. Suggested method to include vacuuming, damp wiping and tacki-wiping as required Filters to be changed prior to ISO cleaning.
IT Cabinets:	All accessible surfaces external and internal to be cleaned. Suggested method to include vacuuming, damp wiping and tacki-wiping as required.
Cages, Doors, Walls	All accessible areas to be cleaned. Suggested method vacuuming.
Equipment	All accessible surfaces external and internal to be cleaned. Suggested method to include vacuuming, damp wiping and tacki-wiping as required.

After the clean a full ISO 14644-3 2022 validation survey will be conducted using our calibrated air particulate reader from this data an ISO 14644-1 Certificate will be issued.